

EN

#7124 KONUSPOT-50

MOUNTING:

- 1) Screw the tripod (1) onto the spotting scope,
 - 2) To focus, rotate the metal ring (2) until you have obtained the clearest image possible..
 - 3) ZOOM: rotate the metal ring (3) in order to vary the magnification from 15x to 40x. Increased magnification requires adjustment of the focus.
 - 4) Choice of magnification; with an increased magnification there is a decrease in luminosity and a reduction of the magnified area.
- Always begin observation at a low magnification and increase steadily until the best magnification, compatible with the observed subject and its environment is achieved .

TECHNICAL CHARACTERISTICS:

MODEL 7124 PRISMATIC SCOPE • MAGNIFICATION FROM 15X TO 40X • Ø50 MM OBJECTIVE • WITH TABLE TRIPOD.

NEVER AIM THE INSTRUMENT AT THE SUN. NEVER LOOK THROUGH THE INSTRUMENT AT THE SUN

MAINTENANCE:

- Store your equipment in a safe, dry place, ensuring that it is covered and protected from dust.
- Avoid touching the lenses with dirty fingers as the salt and moisture contained in the skin could damage the lenses.
- Do not clean the optic parts if it is not absolutely necessary to do so, as they might suffer damage.
- For cleaning of the lenses, we recommend a soft cloth. In the case of more ingrained dirt, use a soft cloth, without any artificial fibres, soaked with alcohol or ether.

